

### CORRECTION FACTORS FOR COMBUSTIBLE GAS (LEL) SENSORS

#### LEL Correction Factors

RAE Systems LEL sensors (including LEL only sensor and LEL/TC dual-range sensor) can be used for the detection of a wide variety of combustible gases and vapors that exhibit different responses. Because LEL sensors use a diffusion barrier to limit the gas flux to the catalytic bead, high diffusivity compounds tend to have the greatest sensitivity. Therefore small molecules like hydrogen and methane are substantially more sensitive than heavy components like kerosene. The best way to calibrate any sensor to different compounds is to use a standard of the gas of interest. However, correction factors have been determined that enable the user to quantify a large number of chemicals using only a single calibration gas, typically methane or pentane. In our LEL sensors, correction factors (CFs) can be used in one of three ways:

- 1) Calibrate the unit with methane in the usual fashion to read in methane %LEL equivalents. Manually multiply the reading by the correction factor (CF) to obtain the %LEL of the gas being measured.
- 2) Calibrate the unit with methane and then call up the correction factor from the instrument memory or download from a personal computer. The unit will then read directly in %LEL of the gas of interest.
- 3) Calibrate the unit with methane, but input an equivalent, "corrected" span gas concentration when prompted for this value. For example, to read in isopropanol LEL units, apply 20% LEL methane but enter  $20 \times 2.6 = 52$  for the span gas concentration.

#### Oxygen Requirement and Matrix Effects

LEL sensors require oxygen for combustion and cannot be used in environments that contain less than about 12% oxygen. This threshold depends on the combustible gas concentration. For example, for 10% LEL methane, RAE LEL sensors show little or no oxygen dependence down to about 5 vol% oxygen. Humidity and temperature generally have little effect on the sensor response. Increasing temperature increases the response by <6% between 0 and 40°C. Increasing RH decreases the response by 8% between 5 and 95% RH.

#### Methane Sensitivity Changes

The correction factors in this table apply to new sensor. As the sensor becomes used and gradually loses sensitivity, the response to methane may decrease more

rapidly than for higher hydrocarbons. In this case,

the correction factors will gradually decrease, and calibration with methane will tend to over estimate the %LEL of the other gas. Therefore, methane calibration is the safest approach. RAE LEL sensors do not exhibit changes in correction factors in laboratory tests, but may do so under special use conditions. Calibrating with other organic vapors such as propane or pentane is a good way to avoid correction factor changes. The only drawback to this approach is that it is possible to miss methane while still measuring the higher hydrocarbons. If methane is known to be absent under all circumstances, the use of propane or pentane calibration is appropriate.

#### Correction Factors when Calibrating with Non-methane Compounds

To obtain correction factors for other span gases, simply divide the value on the methane scale in the table by the methane value for the span compound. For example, to obtain CFs on the n-pentane scale, divide all the numbers in the table by 2.2. Thus, when calibrating with n-pentane the new CF for acetylene is  $2.8/2.2 = 1.3$ , and the new CF for ammonia is  $0.8/2.2 = 0.4$ . Note that this calculation is done internally in RAE instruments that have separately selectable span and measurement gases. Therefore, in these cases, simply enter the span and measurement compounds (without changing the CFs), and the unit will automatically calculate and apply the new factor.

Chemical	100% LEL (Vol%)	LEL CF*
Acetaldehyde	4.0	1.8
Acetic acid	4.0	3.4
Acetic Anhydride	2.7	2.0
Acetone	2.5	2.2
Acetylene	2.5	2.8
Allyl Alcohol	2.5	1.7
Ammonia	15.0	0.8
Aniline	1.3	3.0
Benzene	1.2	2.2
Butadiene, 1,3-	2.0	2.5
Butane, n-	1.9	2.0
Butane, i-	1.8	1.8
Butanol, n-	1.4	3.0
Butanol, i-	1.7	2.5
Butanol, t-	2.4	1.8



<b>Chemical</b>	<b>100% LEL (Vol%)</b>	<b>LEL CF*</b>	<b>Chemical</b>	<b>100% LEL (Vol%)</b>	<b>LEL CF*</b>
Butene-1	1.6	2.1	Methyl chloride	8.1	1.3
Butene-2, cis	1.7	2.1	Methylcyclohexane	1.2	2.6
Butene-2, trans	1.8	1.9	Methyl ether	3.4	1.7
Butyric acid	2.0	2.4	Methyl ethyl ketone	1.4	2.6
Carbon disulfide	1.3	**	Methyl formate	4.5	1.9
Carbon monoxide	12.5	1.2	Methyl hexane	1.2	2.4
Carbonyl sulfide	12.0	1.0	Methyl mercaptan	3.9	1.6
Chlorobenzene	1.3	3.0	Methylpentane	1.2	2.7
Chloropropane, 1-	2.6	1.8	Methyl propionate	2.5	2.1
Cyanogen	6.6	1.1	Methyl n-propyl ketone (2-pentanone)	1.5	2.7
Cyclohexane	1.3	2.5	Naphthalene	0.9	2.9
Cyclopropane	2.4	1.5	Nitromethane	7.3	2.1
Decane, n-	0.8	3.4	Nonane, n-	0.8	3.2
Dichloroethane, 1,2-	6.2	1.5	Octane, n-	1.0	2.9
Dichloromethane	13.0	1.0	Pentane, n-	1.5	2.2
Dimethylbutane	1.2	2.7	Pentane, i-	1.4	2.3
Dimethylpentane, 2,3-	1.1	2.3	Pentane, Neo-	1.4	2.5
Dimethyl sulfide	2.2	2.3	Pentene, 1-	1.5	2.3
Dioxane, 1,4-	2.0	2.5	Phosphine	1.6	0.3
Ethane	3.0	1.4	Propane	2.1	1.6
Ethanol	3.3	1.7	Propanol, n-	2.2	2.0
Ethene	2.7	1.4	Propene	2.0	1.5
Ethyl acetate	2.0	2.2	Propylamine, n-	2.0	2.1
Ethylamine	3.5	1.4	Propylene oxide	2.3	2.6
Ethyl benzene	0.8	2.8	Propyl ether, iso-	1.4	2.3
Ethyl bromide	6.8	0.9	Propyne	1.7	2.3
Ethyl chloride	3.8	1.7	Toluene	1.1	2.6
Ethyl ether	1.9	2.3	Triethylamine	1.2	2.5
Ethyl formate	2.8	2.4	Trimethylamine	2.0	1.9
Ethyl mercaptan	2.8	1.8	Trimethylbutane	1.2	2.3
Ethyl methyl ether	2.0	2.3	Turpentine	0.8	2.9
Ethyl pentane	1.2	2.4	Vinyl chloride	3.6	1.8
Ethylene oxide	3.0	2.3	Xylene, m-	1.1	2.7
Gasoline,	1.3	2.1	Xylene, o-	0.9	3.0
Heptane, n-	1.1	2.4	Xylene, p-	1.1	2.8
Hexadiene, 1,4-	2.0	1.5			
Hexane, n-	1.1	2.3			
Hydrazine	2.9	2.1			
Hydrogen	4.0	1.1			
Hydrogen cyanide	5.6	2.0			
Hydrogen sulfide	4.0	**			
Isobutene (Isobutylene)	1.8	1.5			
Isopropanol	2.0	2.6			
Jet fuel JP-4, -5, -8	0.7	3.4			
Methane	5.0	1.0			
Methanol	6.0	1.5			
Methyl acetate	3.1	2.2			
Methylamine	4.9	1.3			
Methyl bromide	10.0	1.1			

\* Values in italics are calculated from diffusion properties; values in normal type are confirmed with RAE sensors.

\*\* CAUTION!! On LEL/TC sensors (3R/TC & 4R/TC) CS<sub>2</sub> may cause a large baseline shift and sensitivity loss; for LEL-only sensor (4R), an approximate CF of 3±2 can be used. H<sub>2</sub>S may cause a large baseline shift and sensitivity loss on LEL and TC/LEL sensors.